

Mar. 22 200

43PM

BORZA INSPECTION 780/440-2147

No



Borza Inspections Ltd.

5710 - 17 Street, Edmonton, Alberta, Canada T6P 1S4
Bus: (780) 944-2857 • Fax: (780) 440-2147
24 Hour Service
Edmonton, AB • Fort Nelson, BC • Fort St. John, BC

ISO 9001:2000 - #97-598

February 4, 2005

Viper Rentals & Service Ltd.
Box 1878
High Level, Alberta
T0H 1Z0

CERTIFICATION

Equipment: BJ - MYT Elevator
Borza Inspections Ltd. Stamp No.: M74380
Model No.: 2 7/8" Sliptype #997 - 40 Ton Center Latch
Serial No.: VRS 997
Owner: Viper Rentals & Service Ltd.
Repair Facility: R.S. Machine & Mnfg. Ltd. (W.O. 28232)
Borza File No's: E21771/M75455/M74380

We performed our engineering examination of this elevator on December 30, 2004 and February 1, 2005 at R.S. Machine & Mnfg. Ltd.. The elevator was completely disassembled and sandblasted.

Borza technicians provided magnetic particle inspection services. Final NDT inspection revealed no defects after load test (LTE-0205-28232-0483). New pins were supplied by R.S. Machine & Mnfg.

As a result of our inspections and review of repairs, we believe that this elevator may be safely returned to service within the manufacturer's original specifications.

This certification is valid for 6 years as per CAODC T-94-1/RP-4.0, or until the elevator assembly is damaged by handling or operation.

